Home Performance Assessment Summary Report

HOME PERFORMANCE WITH ENERGY STAR	Smith Home Performance Contracting 1 Address Street, City, ST 00000 • Phone: 000-0000 • Fax: 000-0000 • smithhpc@smithhpc.com
Customer Name:	Customer Phone Number (h):
Customer Address:	Customer Phone Number (w):
City, State, Zip:	Customer Email:
Inspection Date:	Home Performance Analyst:

Your Home Performance Assessment identifies opportunities to improve the performance of your home based on our analysis. This report summarizes the findings, prioritizes recommended improvements, and helps you determine the best improvements for your home.

Findings and Recommendations

	Priority Findings on Existing Conditions	Recommendations for Improvements	
Building Envelope Evaluation	Blower door test:cfm50 Tightness std:cfm50 Leakage pathways observed: Basement/crawl ceiling Interior baseboard/top molding/fireplaces Sill plate Window and door frames Attic floor Attic hatch(es) Band joist between floors Recessed lights Major air leakage bypass(es): Other:	 Reduce leaks by% No recommendations Air seal the following leakage pathways: Bsmnt/crawl penetrations Exposed sill plate Attic penetrations Top wall plates in attic Flue/chimney penetrations Open attic stairs/walls Attic hatch/pulldown Base and ceiling molding Door and window frames Around fireplace/mantle Weatherstrip: doors windows hatches outlets Recessed lights: covers inserts new housings 	
	Duct leakage observed at: OR No ducts in unconditioned space Main trunk connections Duct disconnects/failures at: Branch line connections	 Duct sealing: hours Air flow balancing Include duct blaster test for leakage to outside Repair or reconnect ducts Add return(s) Replace approx% of duct system Duct cleaning No recommendations 	
	Above grade walls R-Value/Inches Insulation Attic (flat) Attic (slope) Kneewall(s)	Insulate in the following locations: R-Value/Inches Insul. Walls	
	Image: Single pane windows Condition: Good Fair Poor Image: Double pane windows Double pane windows Condition: Good Fair Poor Image: Double pane windows Double pane low-e Condition: Good Fair Poor Image: Storm windows Condition: Good Fair Poor Image: Double pane low-e Condition: Good Fair Poor	 Replace windows with a u-value ≤ and solar gain ≤ Replace door(s) w/ Solar screens Other: No recommendations 	
Mechanical Equip. Evaluation	Main heating system is a	 Replace main heating system with new with rated efficiency Replace 2nd heating system with new with rated efficiency Fix/replace condensate line Remove 2nd heating system Install prog. thermostat Replace filter(s) Fix/replace condensate line Other: No recommendations 	

Findings and Recommendations (cont.)					
	Pric	ority Findings on Existing Conditions	Recommendations for Improvements		
Mechanical Equip. Evaluation (cont.)	Space Cooling	Main cooling system is: Central Room Heat pump System efficiency is	 Replace main cooling system with SEER system Replace 2nd cooling system with SEER system Clean/adjust blower Check and adjust charge Clean coils inside/outside Check and adjust airflow Fix/replace condensate line Clean/adjust blower Check and adjust charge Clean coils Check and adjust airflow No recommendations 		
Mechanical	Water Heating	Water heating system is a Estimated system efficiency is or age Condition: O Good Replace Temperature Setting: Size: Gallons Low flow showerheads Yes No	 Replace water heating system with new with rated efficiency Install solar hot water Install low flow showerhead Insulation jacket Other: No recommendations 		
Baseload and Renewables	Appliances and Lighting	Refrigerator Age: O ENERGY STAR Dishwasher Age: O ENERGY STAR Clothes washer Age: O ENERGY STAR Dryer Age: O ENERGY STAR Other: O ENERGY STAR High-use lighting% CFL bulbs ENERGY STAR All lighting% CFL bulbs Renewable opportunities:	 Replace with ENERGY STAR refrigerator Replace with ENERGY STAR dishwasher Replace with ENERGY STAR clothes washer Replace with dryer Install ENERGY STAR CFL bulbs in high-use fixtures Purchase ENERGY STAR CFLs when replacing bulbs Install renewables: 		
Health, Safety, and Durability	e& Combustion Appliance Testing	Heating System Water Heater CO tests Pass Fail Pass Fail Draft tests Pass Fail Pass Fail Spillage tests Pass Fail Pass Fail Ambient CO in living space Pass Fail Pass Fail Ambient CO in CAZ Pass Fail Oven CO test Pass Fail Gas or oil leaks detected Yes No CO Monitor Locations:	No Fix venting issues at:		
	Exhaust Moisture & Vent. Durability	Roof Soffits Other: Sil Interior: Other: Other: Improperly vented, non-operable, or needs ventilation: Master bath 3rd bath Dryer Whole-house 2nd bath Range hood Crawlspace Other: Ommended Measures Summary Other:	Other: Replace/install exhaust fan Install dehumidifier Add humidistat/timer		
Non-Energy Benefits: Estimated Annual KWh Savings					
		nd that the above recommendations do not constitute a binding contract pr • Signature:	roposal. I am interested in receiving such a proposal as a next step Date:		